FORM 101 AMP-TRAP FUSE
MELTING TIME CURRENT DATA
15-2000 AMPS 1000 VOLTS

CAT. NO. A100P(15-30) TYPE-1
A100P(35-2000) TYPE-4,4IL,4TA,4TI

MERSEN

Newburyport, MA 01950

96313



CONTROL NO: 1005
REV: N
FOLDER NO.: 1G
DATE: 6-6-06